

Message

From: Budroe, Thomas [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=079D721E6CF849D4AC2E621F5E22B5FD-BUDROE, THOMAS]
Sent: 1/22/2019 2:32:21 PM
To: Reuben, Peter A (DEC) [peter.reuben@dec.ny.gov]; Lisichenko, Peter [lisichenko.peter@epa.gov]
Subject: RE: Site 108 report

Thanks Pete

From: Reuben, Peter A (DEC) <peter.reuben@dec.ny.gov>
Sent: Tuesday, January 22, 2019 8:26 AM
To: Budroe, Thomas <Budroe.Thomas@epa.gov>; Lisichenko, Peter <lisichenko.peter@epa.gov>
Subject: RE: Site 108 report



The attached plan was not approved by the DEC. See below comments.

- 1) We only allowed berm water to be discharged to the ground surface during the investigation and initial phase of the IRM. As soon as the interior of the berms were disturbed by the IRM the coal tar starting creating sheens and I made them pump the water and treat through the Main Plant system.
- 2) Page 2, Cut Pipes and Plastic Sheeting: the pipes near Tank 2 were cut during the IRM when the demolition of the tanks was still to be completed by TCC. The majority of the tar/water mixture that is there flowed out of the pipes (from the direction of the pump house), not the valve EPA refers to. It is possible that the valve is leaking, but most of the tar/water is from the pipes or what was already within the berm when the IRM started.
- 3) Page 4, Soil Pile Tarping: this is the IRM screened soil. This plan does not make it clear that the soil pile is related to the IRM and that it has been tested, and more importantly that it was derived from listed hazardous waste.
- 4) Page 4, Berm System Monitoring: I have calculated that the berms need 2 feet of freeboard.
- 5) Page 4, ACM Tanks: pipe wrap does contain ACM. TCC did a small asbestos abatement to cut the pipes connecting the tanks.

Margo Ludmer exchanged email with DEC on site 108. I am not sure if she received the full list of documents for this site. Let me know as I may be able to send you a link so you may download the 82.04MB of files.

Pete

Peter Reuben
Environmental Chemist 2, Division of Environmental Remediation

New York State Department of Environmental Conservation
270 Michigan Ave., Buffalo, NY 14203
P: (716) 851-7220 | F: (716) 851-7226 | peter.reuben@dec.ny.gov
www.dec.ny.gov |  | 

From: Budroe, Thomas <Budroe.Thomas@epa.gov>
Sent: Monday, January 21, 2019 10:05 AM
To: Lisichenko, Peter <lisichenko.peter@epa.gov>
Cc: Reuben, Peter A (DEC) <peter.reuben@dec.ny.gov>
Subject: Re: Site 108 report

ATTENTION: This email came from an external source. Do not open attachments or click on links from unknown senders or unexpected emails.

Thanks Pete

Sent from my iPhone

On Jan 18, 2019, at 5:48 PM, Lisichenko, Peter <lisichenko.peter@epa.gov> wrote:

Thank you Pete!

Sent from a mobile device

Peter Lisichenko

On-Scene Coordinator

Region 2 USEPA

347-276-6251

On Jan 18, 2019, at 3:26 PM, Reuben, Peter A (DEC) <peter.reuben@dec.ny.gov> wrote:

As you requested, see attached.

Peter Reuben

Environmental Chemist 2, Division of Environmental Remediation

New York State Department of Environmental Conservation

270 Michigan Ave., Buffalo, NY 14203

P: (716) 851-7220 | F: (716) 851-7226 | peter.reuben@dec.ny.gov

www.dec.ny.gov | <image001.png> | <image002.png>

<Remedial Investigation Report Site 108.pdf>